


# New Standards to Find & Measure Infiltration and Test & Certify Cured-In-Place Pipe (CIPP)

*Mackenzie App, Eastern Field Sales Manager and Operations Specialist Electro Scan Inc.*



# New Standards for Testing & Certifying Cured-In-Place Pipe (CIPP) As Watertight

1. Introduction
2. What the FELL?
3. Case Studies
4. Wrap-Up





# Part 1

The word "Intro" is rendered in large, three-dimensional gold letters with a polished, reflective surface. The letters are placed on a dark, textured wooden background with prominent vertical grain patterns. The lighting creates highlights on the top and right edges of the letters, giving them a sense of depth and weight. The overall composition is clean and professional, serving as a visual introduction to the content.



**LIVE**

**BREAKING**

**NEWS**

**BREAKING NEWS**

**Failed Trenchless UV-Liner Causes Massive Flooding**

**Homeowners Evacuated as Contractor to be Held Responsible**



**LIVE**




**Heavy Rain Cause 50ft Section of Newly Installed Sewer to Backup Into Million Dollar Homes**




# Defective Sewer Lateral Connections







Leak



Soakage



# Milestones of New Acceptance Standards

2004	<b>WERF Study</b> – An Examination of Innovative Methods Used in the Inspection of Wastewater Systems, Focused Electrode Leak Location System (Fell-41).
2006	<b>ASTM F2550-06 Approved</b> – First Presentations at ASCE Pipeline Conference.
2009	<b>Condition Assessment of Wastewater Collection Systems</b> EPA/600/R-09/049, 4.3.1 Electrical Leak Location Method, published.
2010	<b>State of Technology for Rehabilitation of Wastewater Collection Systems</b> – EPA/600R-10/078, including FELL is published. Ken Kerri contacts Chuck Hansen.
2011	<b>USEPA Field Demonstration</b> – Condition Assessment Technologies for Wastewater Collection Systems. First benchmarking CCTV and FELL.
2013	<b>ASTM F2550-13 Approved</b> – Added recommendation for scanning all Pre- and Post-Rehabilitation, including Cured-In-Place Pipe. <b>NASTT Best New Product Award; WEF Best Innovation Award</b>
2014	Ken Kerri, PhD, PE Updates <b>O&amp;M Wastewater Collection Systems</b> manual. FELL added to first EPA Consent Decree (EBMUD).
2015	<b>Adoption by UK-based WRc</b> – Developers of NASSCO CCTV Codes.
2017	Japan Sewer Collection System Maintenance Association ( <b>JASCOMA</b> ), Certification for Water Tightness.
2018	<b>AWWA M77 Standard &amp; ASTM F2550-13 (2018) Reapproved.</b> Condition Assessment of Water Mains, Includes FELL.
2019	<b>IKT</b> (Germany) expected to publish CIPP research study that utilizes FELL.







**Designation: ASTM F2550-13 (2018)**

## **Standard Practice for Locating Leaks in Sewer Pipes By Measuring the Variation of Electric Current Flow Through the Pipe Wall<sup>1</sup>**

This standard is issued under the fixed designation F2550; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon ( $\epsilon$ ) indicates an editorial change since the last revision or reapproval.

### **INTRODUCTION**

Infiltration of groundwater into a sewer through defects in the pipe can considerably increase the operation and capital costs of a sewer system. Exfiltration of sewage out of a sewer pipe may cause degradation of aquifers and shoreline waters. **Accurate location, measurement, and characterization of all potential pipe leak defects are essential inputs for cost-effective design, testing, and certification of pipe repairs, renewal, and new construction.** While commonly used sewer leak assessment methods, such as air and water pressure testing, represent cost effective methods to provide overall Pass/Fail pipe assessments, their inability to provide accurate location and size of leaks, particularly at individual joints and service connection, limit their use in remediation and rehabilitation decision support.





# M77 Manual of Practice: Condition Assessment of Water Mains

## Chapter 7

# Leak Detection

## Low Voltage Conductivity Testing

*Pipe materials.* Since low voltage conductivity testing is based on the difference of the high electrical resistivity properties of the pipe walls (i.e., non-conductive) vs. the low electrical resistivity of the earth surrounding the pipe, non-conductive pipe materials work best with this testing method, including asbestos cement (AC), cured-in-place pipe (CIPP), fiberglass-reinforced pipe (FRP), high-density polyethylene (HDPE), polyvinyl chloride (PVC), and reinforced concrete pipe (RCP).

2018



**wrc** infrastructure developers of NASSCO standards.

Case Study - Sewer Infiltration Identified and Quantified



# PIPELINE ASSESSMENT CERTIFICATION PROGRAM

REFERENCE MANUAL  
VERSION 7.0.0 - MAY 2015  
© 2015 NASSCO



STANDARD FOR THE REHABILITATION OF UNDERGROUND UTILITIES



## Table of Contents

References	ix	Code Column	3-3
Introduction	xi	Continuous Defect Column	3-4
Section 1 - Introduction and Need for Certification	1-8	Value Column	3-13
RACP Overview	1-1	Joint Column	3-15
Origin of Condition Codes	1-1	Cumulative Defect Column	3-16
Reasons for TV Inspection	1-2	Image Reference Column	3-17
Why Standardization is Important	1-3	Remarks Column	3-18
General Approach to TV Inspection Using RACP	1-4	Sample RACP Inspection Form	3-18
Supplemental Technologies	1-6	Section 4 - Structural Defect Coding	4-8
Background to Technical Issues	1-11	Structural Defects	4-1
RACP Inspection Form	1-22	Crack (C)	4-3
RACP Inspection Deliverables	1-23	Fracture (F)	4-5
Section 2 - RACP Header Section	2-0	Broken (B)	4-17
RACP Inspection Form Header Section Instructions	2-1	Hole (H)	4-21
General Guidelines When Completing OCTV Inspection Form Header Section	2-1	Deformed (D)	4-24
OCTV Inspection Header Information	2-2	Collapse (R)	4-26
1. General Information	2-2	Joint (J)	4-43
2. Location	2-8	Surface Damage (S)	4-51
3. Pipe	2-12	Living Features (LF)	4-57
4. Measurements	2-15	Weld Failure (WF)	4-62
Sketch	2-27	Point Repair (RP)	4-65
Section 3 - RACP Details Section	3-0	Breakout	4-67
RACP Inspection Form Details Section	3-1	Section 5 - Operation and Maintenance Coding	5-8
Initial Coding	3-1	Operation and Maintenance Defects	5-1
Final Coding	3-2	Deposits (D)	5-3
Distance Column	3-2	Roots (R)	5-11
Value Reference Column	3-3	Infiltration (I)	5-15
		Continuous Defects (CD)	5-21
		Severs (S)	5-45
		Grout Test and Seal (G)	5-46
		Section 6 - Construction Features Coding	6-8

WRc

WRc  
Pier Adjustment

WRc  
Maintenance

## Acknowledgments

NASSCO highly values all input from the Water Research centre (WRc) team. In particular, NASSCO would like to acknowledge the efforts of the following WRc professionals:

Andrew Drinkwater

Peter Henley

Karen Willmott

Melanie Monk

Line Poinel


Ian Walker

Phil Wildbore

# **CAMERAS MISS 80-100% OF LEAKS.**

**CCTV Can't  
Look Inside Joint  
or Turn 90-Degrees**

**CCTV Can't See Inside  
But FELL Can!**







Distance:	392.4
CC:	Crack Circumferential
Clock from:	7
Clock to:	10
Rating:	
S/M/L:	
Dimension1	
Dimension2	
%	
Remarks:	

**CCTV  
Can't Tell If  
A Crack Goes  
Through a Pipe,  
But FELL Can.**



02.11.2015

09:39

25'11"




**CCTV Can't Tell If A  
Service Connection  
Leaks, But FELL Can.**

Tap Factory Active

115.5 FT

8"






# WATERTIGHT

electro<sup>o</sup>scaninc.

Distance From Start of Scan (In Feet)





**LEAKS**

electro<sup>scan</sup>inc.

Distance From Start of Scan (In Feet)

## Focused Electrode Leak Location (FELL)

### Selected Cured-In-Place Pipe Assessments – By CIPP Supplier

[illegible]

- [illegible]



# CIPP Reporting By Contractor

Edit Pipe Liner History | Critical Sewer X

[←](#) [→](#) [↻](#) [🏠](#) [www.criticalsewers.com/edit-pipe-liner-history](#) [⋮](#) [📧](#) [★](#)  [🔍](#) [📅](#) [☰](#)

Home ES Internal Upload Scans Edit Scans Export Data Support Log Out

### Pipe Liner History

KC Water

#	Scan Date	Customer	Project	Job	Mainline ID	Pipe ID	Pipe Type	Pipe Dia.
<input type="radio"/>	3/29/2018	KC Water	Southeast		436 - 439	436 - 439	CIPP	8
<input checked="" type="radio"/>	3/29/2018	KC Water	River Basin		434 - 435	434 - 435	CIPP	8
<input type="radio"/>	3/29/2018	KC Water	Downtown		455 - 456	455 - 456	CIPP	8
<input type="radio"/>	7/15/2013	KC Water	Airport		MH1 - MH2	MH1 - MH2	XXX	8

To enter Liner History for this pipe, select values for all of the options below and click Save.

CIPP Supplier:

CIPP Installer:

Liner Type:



Curing:

TBD  
Hot Water  
UV Light  
Ambient Cured  
Steam

TBD  
Abel Recon  
rdner  
am Services, Inc.  
ewer  
e Rehabilitation


## Part 2

# What the FELL?







# Combining Electricity & Water To Certify CIPP?



# Elementary School








# “If a Pipe Leaks Electricity, It Leaks Water.”



- *Elementary Geophysics*



## Torricelli's Law



$$v_1 = \sqrt{2g(y_2 - y_1)}$$

$$P_1 = P_2$$

$$P_1 + \left(\frac{1}{2}\right)\rho(v_1)^2 + \rho g y_1 = P_2 + \left(\frac{1}{2}\right)\rho(v_2)^2 + \rho g y_2$$

## Ohm's Law


$$E = IR ; I = E/R ; R = E/I$$

Where:

“E” volts

“I” amps

“R” ohms





# Basic Science ohm's Law

No Electric Current Able  
to Pass Through Liner.  
No Leakage.

**GOOD  
CIPP**



$$E = IR ; I = E/R ; R = E/I$$

Where:

*"E" volts*

*"I" amps*

*"R" ohms*



# Basic Science Ohms Law



Electric Current Able to Pass  
Through Liner Wall.  
Leak Located & Measured.

**BAD  
CIPP**






# FELL is a 'Holiday' Test...




ASTM D5162  
ASTM D4787  
NACE RP01-88




# ...For Full-Length Pipes.






















# FELL Survey - Field Operation

Evaluates 360° of a  
Pipe Wall Finding &  
Measuring All  
Openings  
to Ground

Electro Scan Inspection Van

Electric  
Current  
Meter

Voltage  
Source

Grounding  
Source


Water = Conductor

Probe Cable

Electro Scan Probe

Sliding Funnel Plug


Jet Truck






# Water — Must Surround The Probe To Allow Electrical Current To Assess The Wall of the Pipe.

## Funnel Cone Recommended For Pipe Diameters Up To 15"




Connected to a jet hose, allows water to be temporarily held back to create a moving reservoir around probe.

## For Larger Diameters, Pipe Wall Assessed at Water Line & Below





# What About Electrical Interference?








# Repeatability Test


## Same Pipe & Same Equipment




Scan 1



Scan 10





Scan 15







# 60-Days

EPA Repeatability Example – Same Pipe, Same Equipment, Same Field Crew






## MDWASD Example – Different CCTV Cables/Reels, FELL Probes, Crews, Software Version




# How Are Laterals Tested?

3-6" Diameter Pipes Up To 200 LF





# How Are Manholes Tested?



**amazon** web services      **critical** manhole      **rackspace** HOSTING

Machine Intelligent      Pre & Post Rehab Assessments      Quantify Reduction of Suspected Flows      Easily Prioritize Rehabilitation


No Arguing Over CCTV Images      Watertight Certification of Contractor's Work      Defect Flows by Location and GPM      Integrate with Innovyze InfoMaster®

**Quantify GPM Reductions in Minutes**

**NEW** Find & Measure Leaks in GPM Missed By Digital CCTV Side Scanners


A composite image illustrating the manhole testing process. It includes a person in a yellow suit working in a manhole, a computer monitor displaying data, and a diagram of a manhole with a sensor probe. The diagram shows a cross-section of the manhole with a sensor probe inserted into the water. The probe is connected to a computer system that displays data on the monitor. The diagram also shows a red 'NEW' label and text that reads 'Find & Measure Leaks in GPM Missed By Digital CCTV Side Scanners'.





FIRE WALL



criticalsewers®



FIRE WALL



# Results In Minutes





# Measuring Reduction In Flows

Date		Pipe ID	Diameter	Pipe Type								
11/19/2015	A	1-35 - 1-34	8	VCP	395.1	64	2	1	16.46	23,702	39,592	
3/16/2016	B	1-35 - 1-34	8	CIPP	391.3	0	0	2	15.22	21,917	36,968	
6/29/2016	C	1-35 - 1-34	8	CIPP	394.8	1	0	0	0.20	288	481	
					Distance (ft)	Small Defects	Medium Defects	Large Defects	GPM	GPD	GPD/IDM	


Test

A



Inspect

B



Accept



C




electro<sup>o</sup>scan



METROPOLITAN  
SEWER DISTRICT  
of greater  
CINCINNATI



查克·汉森



الكترو سكان



# Warren Township, NJ

WARREN TOWNSHIP SEWERAGE AUTHORITY  
STAGE I/II SEWER SERVICE AREA – COLLECTION SYSTEM REHABILITATION  
CONTRACT NO. 60  
WARREN TOWNSHIP, NJ

SECTION 33 01 12.11

LEAKAGE DETECTION – FOCUSED ELECTRODE LEAK LOCATION (FELL)  
INSPECTION AND TESTING

PART 1 - GENERAL

1.01 REFERENCE STANDARDS

- A. Comply with applicable provisions and recommendations pursuant to the following standards:
  - 1. ASTM F2550 – Standard Practice for Locating Leaks in Sewer Pipes by Measuring the Variation of Electric Current Flow Through the Pipe Wall.
- B. Acceptance Testing:
  - 1. General
    - a. Lined pipes shall be FELL tested as described in this section.
    - b. Any damage caused to properties due to wastewater handling and/or wastewater backup while FELL testing shall be the responsibility of the Contractor.
  - 2. Testing Equipment
    - a. FELL Testing shall be performed utilizing a low-voltage, tri-electrode array inspection probe, approved by the manufacturer for the respective pipe diameter. This equipment and process will be in full compliance with ASTM F2550 with capabilities as outlined in this Standard. For pipes with diameters below 16”, a Sliding Funnel Plug should be used, so as to limit the amount of water used and prevent against backups. All equipment should be calibrated daily to verify that electrodes are operating within manufacturer’s specified current range.
  - 3. Focused Electrode Leak Locating (FELL) Procedure

# FELL TESTING & ACCEPTANCE SPECIFICATION

Bid Item 60-16 FELL Inspection and Testing: The Bidder hereby proposes the following unit price per LF price for all FELL Inspection and Testing (post liner installation), including submittals, and any other Division 1 requirements; Work covered by Divisions 2 through 33 as applicable; testing, warranties, guarantees, and all other work incidental to the full completion of the Project as set forth in the Contract Documents; excepting that covered by Allowance Items. The total estimated linear footage of FELL Inspection and Testing is 12,407 LF.

Unit Price per linear foot, Bid Item 60-16

\_\_\_\_\_ \$ \_\_\_\_\_ per L.F.  
(Words) (Numbers)

60-16	FELL Inspection and Testing	12,407	LF
-------	-----------------------------	--------	----

# San Francisco, CA



	AGENCY	CONTRACT	PROJECT NAME	ENGINEERS ESTIMATE	TOTAL FOOTAGE
1	SFPUC	WW-633	Various Locations Sewer Replacement No. 2	\$ 7,300,000	8,770
2	SFDPW	2501J	University St and Sunnydale Ave Pavement Renovation and Sewer Replacement	2,456,344	444
3	SFDPW	2657J	Octavia Blvd and Oak Street Enhancement	1,008,481	373
4	SFPUC	WW-649	Paul Avenue Sewer Replacement	770,000	912
5	SFPUC	WW-629	Various Locations Sewer Replacement No. 1	8,000,000	9,403
6	SFPUC	WW-636	Various Locations Sewer Replacement No. 4	5,500,000	5,319
7	SFPUC	TBD	Mariposa Avenue	2,000,000	450
8	SFDPW	2781J	Proposition K Curb Ramps FY 15-16	540,000	100
9	SFDPW	2731J	Filbert St and Leavenworth Street Pavement Renovation and Sewer Replacement	7,300,000	6,447
10	SFDPW	2300J	California Laurel Village Improvement Project	3,500,000	1,322
11	SFPUC	7-10	Various Locations Sewer Replacement No. 3	900,000	7,101
12	SFDPW	2533	Grant Avenue Pavement Renovation and Sewer Replacement	1,000,000	1,340
13	SFDPW	2500	Various Locations Pavement Renovation and Sewer Replacement	1,000,000	7,172
14	SFDPW	2508	Various Locations Pavement Renovation and Sewer Replacement	1,000,000	4,128
15	SFDPW	5826	Clayton, Clipper, & Portola Pavement/Sewer/Water Renovation	12,900,000	4,282
16	MTA	1303	SF MTA 22 Fillmore Transit Priority Project	67,000,000	3,195
17	SFPUC	WW-637	Various Locations Sewer Replacement and Pavement Renovation No. 5	4,400,000	4,367
18	SFDPW	2501	Various Locations Pavement Renovation and Sewer Replacement No. 31A	2,000,000	1,068
19	SFDPW	2507	University Avenue Pavement Renovation and Sewer Replacement	10,000,750	2,564
20	SFDPW	5826	Alameda Avenue Pavement Renovation and Sewer Replacement	3,000,000	1,300
21	SFDPW	2501	University Avenue Pavement Renovation and Sewer Replacement	18,000,000	2,906
22	SFPUC	WD-2692	Sewer Replacement on Geary Boulevard From 32nd to 48th Avenues	8,000,000	1,538
23	SFPUC	WW-674	Geary Boulevard Sewer & Water Improvements	14,500,000	8
24	SFPUC	WW-611	Cutler Ave, Lower Great Hwy, Sloat Blvd, & Wawona Street Sewer Replacement	2,300,000	1,412
25	SFPUC	WW-627	Baker Beach Green Streets	6,000,000	192
26	SFDPW	8473	San Bruno Avenue Multimodal Improvement Project	1,500,000	600
27	SFPUC	TBD	Hunters Point Shipyard Development	NA	17,563
28	SFDPW	8792	Various Locations Pavement Renovation No. 37 and Sewer Replacement	11,700,000	7,092
29	SFDPW	1032	Various Locations Pavement Renovation No. 39 and Sewer Replacement	10,400,000	3,976
30	SFDPW	7417	Parkmerced/Twin Peaks/Mt Davidson Manor Residential Street Resurfacing	5,100,000	1,671
<b>TOTAL SFPUC &amp; SFDPW PROJECTS</b>				<b>\$ 242,599,576</b>	<b>107,015</b>

**+30 Construction Bids Since January 2017**




# Part 3

## CASE STUDIES


electro  
scaninc.

# EPA Regions





# 1. CIPP ASSESSMENT






# FELL

Electro Scan  
**8 Defects**  
**6.19 GPM**

**4 Service Connections**  
**Leak-Free**  
**&**  
**4 Service Connections**  
**Defects**



0'  
6'  
10'

Upstream Manhole  
Lateral @ 10 o'clock  
Lateral @ 3 o'clock

55.2'  
56.8'

Lateral @ 9 o'clock  
Lateral @ 9 o'clock

127.7'  
141.3'

Lateral @ 3 o'clock  
Lateral @ 10 o'clock

186.7'

Lateral @ 9 o'clock

234.4'

Lateral @ 2 o'clock


326.4'

Downstream Manhole

# CCTV

**CCTV**  
**ZERO Callouts**  
**Contributing**  
**to Infiltration**

# FELL & CCTV




## Significant Leaks at 4 Service Connections!





# 2. VCP & CIPP ASSESSMENT



# 2. VCP & CIPP ASSESSMENT

	Scans	Footage	Total Defects	GPM	GPD
Total:	8	1,529	52	166.6	239,904


Date	Mainline ID	Pipe ID	Pipe Type	Diameter								
1/19/2018	22165 - 22164	22165 - 22164	VCP	10	322.7	18	7	11	112.07	161,381	264,072	
	22164 - 22163	22164 - 22163	VCP	10	86.2	0	1	1	1.27	1,829	11,199	
	22163 - 22162	22163 - 22162	CIPP	10	305.5	0	2	1	23.85	34,344	59,357	
4	22162 - 22161	22162 - 22161	CIPP	10	291.0	1	2	1	21.17	30,485	55,322	
	22161 - 22160	22161 - 22160	CIPP	10	49.4	0	0	0	0.00	0	0	
	22160 - 22159	22160 - 22159	CIPP	10	93.0	0	0	0	0.00	0	0	
7	22159 - 22158	22159 - 22158	CIPP	10	100.7	5	0	0	0.76	1,094	5,737	
	22158 - 22157	22158 - 22157	CIPP	10	280.2	1	1	0	7.48	10,771	21,119	
					Distance (ft)	Small	Medium	Large	GPM	GPD	0K 200K 400K GPD IDM	



# Defects at Lateral v. Liner Defects

DEFECTS		% OF DEFECT LENGTHS		GPM SUMMARY		DIAMETER & DISTANCE		OPERATOR INFO	
Small	1	<div><div></div></div> 0.00080		Minor	0.600	10		Tech Electroscan Project Demo Job Demo	
Medium	2	<div><div></div></div> 0.00740		Moderate	0.000				
Large	1	<div><div></div></div> 0.00310		Severe	20.570				
All Defects	4	<div><div></div></div> 0.01130		Total GPM	21.170	291.00 ft			
				GPD	<div><div></div></div> 30,485				
				GPD IDM	<div><div></div></div> 55,322				
				Minor %	2.83%	0100200300			
				Moderate %	0.00%				
				Severe %	97.17%				


**DEFECT CURRENT** Mainline ID: 22162 - 22161 Pipe ID: 22162 - 22161 Diameter: 10 inches Pipe Type: CIPP Soil Type: Sandy Clay Loam Ground Condition: Snow



# Defects at Lateral v. Liner Defects

DEFECTS		% OF DEFECT LENGTHS		GPM SUMMARY		DIAMETER & DISTANCE		OPERATOR INFO	
Small	1	<div><div></div>0.00080</div>		Minor	0.600	10		Tech Electroscan Project Demo Job Demo	
Medium	2	<div><div></div>0.00740</div>		Moderate	0.000				
Large	1	<div><div></div>0.00310</div>		Severe	20.570				
All Defects	4	<div><div></div>0.01130</div>		Total GPM	21.170	291.00 ft			
				GPD	<div><div></div>30,485</div>				
				GPD IDM	<div><div></div>55,322</div>				
				Minor %	2.83%				
				Moderate %	0.00%				
				Severe %	97.17%				
						0100200300		Atmospheric Test	Scan Start
								1/19/2018 6:13:51 AM	1/19/2018 7:08:36 AM

**DEFECT CURRENT** Mainline ID: 22162 - 22161 Pipe ID: 22162 - 22161 Diameter: 10 inches Pipe Type: CIPP Soil Type: Sandy Clay Loam Ground Condition: Snow



Bad  
Lateral



Bad  
Lateral



Bad  
Liner




Good  
Lateral






7

# CIPP Pinhole Leaks & Liner Soakage





# 3. VCP & CIPP Assessment





# 3. VCP & CIPP Assessment

	Scans	Footage	Total Defects	GPM	GPD
Total:	5	993	85	72.55	104,472

## Listed In Inspection Order

Date	Mainline ID	Pipe ID	Pipe Type	Diameter								
6/20/2018	3-11 - 3-10	3-11 - 3-10	VCP	8	234.2	22	1	0	9.19	13,234	37,297	
	3-10 - 3-135	3-10 - 3-135	VCP	8	237.6	33	1	0	7.81	11,246	31,243	
	3-9 - 3-8	3-9 - 3-8	CIPP	8	234.0	17	3	2	33.40	48,096	135,669	
	3-134 - 3-134.5	3-134 - 3-134.5	CIPP	8	93.3	3	0	2	14.42	20,765	146,852	
	3-134.5 - 3-7	3-134.5 - 3-7	CIPP	8	193.5	0	0	1	7.73	11,131	37,957	

## Ranked By GPM

Date	Mainline ID	Pipe ID	Pipe Type	Diameter								
6/20/2018	3-9 - 3-8	3-9 - 3-8	CIPP	8	234.0	17	3	2	33.40	48,096	135,669	
	3-134 - 3-134.5	3-134 - 3-134.5	CIPP	8	93.3	3	0	2	14.42	20,765	146,852	
	3-11 - 3-10	3-11 - 3-10	VCP	8	234.2	22	1	0	9.19	13,234	37,297	
	3-10 - 3-135	3-10 - 3-135	VCP	8	237.6	33	1	0	7.81	11,246	31,243	
	3-134.5 - 3-7	3-134.5 - 3-7	CIPP	8	193.5	0	0	1	7.73	11,131	37,957	


10 Yr-Old CIPP Worse Than 50 Yr-Old VCP

# A. 2008 CIPP Worse Than 1968 VCP

DEFECTS		% OF DEFECT LENGTHS		GPM SUMMARY		DIAMETER & DISTANCE		OPERATOR INFO	
Small	17	<div><div></div></div> 0.01290		Minor	6.350	8		Tech Electroscan Project DEMO Job DEMO	
Medium	3	<div><div></div></div> 0.00340		Moderate	7.050				
Large	2	<div><div></div></div> 0.01080		Severe	20.000				
All Defects	22	<div><div></div></div> 0.02710		Total GPM	33.400				
				GPD	<div><div></div></div> 48,096	234.00 ft		Atmospheric Test 6/20/2018 9:13:51 AM	
				GPD IDM	<div><div></div></div> 135,669				
				Minor %	14.47%				
				Moderate %	16.07%				
				Severe %	69.46%			Scan Start 6/20/2018 11:02:00 AM	


DEFECT CURRENT

Mainline ID: 3-9 - 3-8   Pipe ID: 3-9 - 3-8   Diameter: 8 inches   Pipe Type: CIPP   Soil Type: Clay Loam   Ground Condition: Dry



WATER HEIGHT AND PROBE SPEED


Mainline ID: 3-9 - 3-8   Pipe ID: 3-9 - 3-8   Diameter: 8 inches   Pipe Type: CIPP   Soil Type: Clay Loam   Ground Condition: Dry





# FELL

Electro Scan  
**22 Defects**  
**33.4 GPM**



# CCTV

16.8' L3 – Lateral 3

73.6' L3 – Lateral 3

125.1' L9 – Lateral 9

189.8' L3 – Lateral 3

233.9' Downstream Manhole MH#3-8

CCTV  
**ZERO (0)**  
**Structural**  
**Defects**

# B. CIPP Assessment: Liner Leaks at Most Host Pipe Joints

DEFECTS

Small	25
Medium	0
Large	1
All Defects	26

% OF DEFECT LENGTHS

0.02560

0.00000

0.00660

0.03220

GPM SUMMARY

Minor	9.400
Moderate	2.880
Severe	8.580
Total GPM	20.860
GPD	30,038
GPD IDM	81,678
Minor %	45.06%
Moderate %	13.81%
Severe %	41.13%

DIAMETER & DISTANCE

10

194.00 ft

0100150200

OPERATOR INFO

Tech Electroscan

Project

DEMO

Job

DEMO


Atmospheric Test

Scan Start


10/12/2018 10:05:25 AM

10/12/2018 10:05:44 AM

**DEFECT CURRENT** Mainline ID: 307887 - 307878 Pipe ID: 307887 - 307878 Diameter: 10 inches Pipe Type: CIPP Soil Type: Ground Condition: Dry



**WATER HEIGHT AND PROBE SPEED** Mainline ID: 307887 - 307878 Pipe ID: 307887 - 307878 Diameter: 10 inches Pipe Type: CIPP Soil Type: Ground Condition: Dry






# FELL

# CCTV

CCTV Date  
08/03/2017

Electro Scan  
**26 Defects**  
**20.8 GPM**



0'

Upstream Manhole 307887

100.8

Tap Factory Made Active

134.6

Tap Factory Made Active

170.7


Tap Factory Made Active

209.5'

Downstream Manhole 307878

CCTV  
**ZERO (0)**  
**Structural**  
**Defects**

# C. CIPP Lateral, Liner, and Pinhole Defects









# Electro Scan Field Results

	Scans	Footage	Total Defects	GPM	GPD							
Total:	5	1,037	220	112.89	162,562							
Date	Mainline ID	Pipe ID	Pipe Type	Diameter								
10/9/2018	1916 - 2787	1916 - 2787	VCP	8	<div><div></div></div> 206.13	<div><div></div></div> 53	<div><div></div></div> 4	<div><div></div></div> 1	<div><div></div></div> 41.87	<div><div></div></div> 60,293	<div><div></div></div> 193,048	
	2787 - 2789	2787 - 2789	VCP	8	<div><div></div></div> 223.67	<div><div></div></div> 86	<div><div></div></div> 5	<div><div></div></div> 1	<div><div></div></div> 36.23	<div><div></div></div> 52,171	<div><div></div></div> 153,942	
	2789 - 1915	2789 - 1915	VCP	8	<div><div></div></div> 216.23	<div><div></div></div> 19	<div><div></div></div> 1	<div><div></div></div> 0	<div><div></div></div> 7.03	<div><div></div></div> 10,123	<div><div></div></div> 30,899	
	4	1915 - 2788	1915 - 2788	VCP	8	<div><div></div></div> 215.06	<div><div></div></div> 19	<div><div></div></div> 1	<div><div></div></div> 1	<div><div></div></div> 14.94	<div><div></div></div> 21,514	<div><div></div></div> 66,024
	5	2788 - 5156	2788 - 5156	VCP	8	<div><div></div></div> 176.40	<div><div></div></div> 27	<div><div></div></div> 2	<div><div></div></div> 0	<div><div></div></div> 12.82	<div><div></div></div> 18,461	<div><div></div></div> 69,072
					Distance (ft)	Small	Medium	Large	GPM	GPD	OK 400K GPD IDM	




Electro Scan




**21 Defects**  
**14.9 GPM**


CCTV

**2 Callouts**  
**Identifying**  
**Infiltration**







**LARGEST DEFECTS ARE JOINTS!!**

# Worst 2 Defects = 76% of Estimated Defect Flow

	Defects	Length (ft)	GPM	% of GPM	GPD	GPD/IDM
Total:	21	2.956	14.920	100%	21,485	65,935

**DEFECT BY LOCATION** Mainline ID: 1915 - 2788 Pipe ID: 2789 - 1915 Diameter: 8 inches Pipe Type: VCP Soil Type: Clay Loam Ground Condition: None **Ranked By GPM**

Defect Grade	Defect Start (ft)	Defect End (ft)	Length (ft)	GPM	% of GPM	GPD	GPD/IDM
L	56.50	57.46	0.96	6.39	42.77%	9,202	28,239
M	200.25	201.09	0.84	5.03	33.67%	7,243	22,229
S	211.31	211.46	0.14	0.57	3.82%	821	2,519
S	92.78	92.97	0.19	0.48	3.21%	691	2,121
S	157.24	157.34	0.10	0.30	2.01%	432	1,326
S	139.34	139.44	0.10	0.28	1.87%	403	1,237
S	124.80	124.89	0.10	0.25	1.67%	360	1,105
S	24.82	24.86	0.05	0.21	1.41%	302	928
S	20.04	20.11	0.07	0.19	1.27%	274	840
S	175.34	175.41	0.07	0.19	1.27%	274	840
S	134.47	134.54	0.07	0.16	1.07%	230	707
S	62.64	62.69	0.05	0.13	0.87%	187	575
S	77.21	77.26	0.05	0.13	0.87%	187	575
S	158.78	158.83	0.05	0.12	0.80%	173	530
S	163.65	163.70	0.05	0.12	0.80%	173	530
S	2.28	2.30	0.02	0.10	0.67%	144	442
S	29.66	29.69	0.02	0.07	0.47%	101	309
S	92.32	92.35	0.02	0.07	0.47%	101	309
S	144.91	144.91	0.00	0.06	0.40%	86	265
S	129.64	129.64	0.00	0.04	0.27%	58	177
S	92.47	92.47	0.00	0.03	0.20%	43	133

## DEFECTS

Small	27
Medium	2
Large	0
All Defects	29

## % OF DEFECT LENGTHS

0.01870
0.00330
0.00000
0.02200


## GPM SUMMARY

Minor	5.800
Moderate	7.020
Severe	0.000
Total GPM	12.820
GPD	18,461
GPD IDM	69,072
Minor %	45.24%
Moderate %	54.76%
Severe %	0.00%

## DIAMETER &amp; DISTANCE


8

176.00 ft




## DEFECT CURRENT

Mainline ID: 2788 - 5156 Pipe ID: 2789 - 1915 Diameter: 8 inches Pipe Type: VCP Soil Type: Clay Loam Ground Condition: Dry



## WATER HEIGHT AND PROBE SPEED

Mainline ID: 2788 - 5156 Pipe ID: 2789 - 1915 Diameter: 8 inches Pipe Type: VCP Soil Type: Clay Loam Ground Condition: Dry






Electro Scan



**29 Defects**  
**12.8 GPM**

CCTV

**3 Callouts**  
**Identifying**  
**Infiltration**

# LEAKING JOINTS AND LATERALS THROUGHOUT.

CCTV Date  
10/10/2018



Part 4

# Wrap Up



electro  
scaninc.



# Included in EPA Consent Decrees Since 2014

**EPA** United States Environmental Protection Agency

[Learn the Issues](#) [Science & Technology](#) [Laws & Regulations](#) [About EPA](#)

Search EPA.gov

**Enforcement** [Contact Us](#) [Share](#)

[Enforcement Home](#)  
[Enforcement Basics](#)  
[National Enforcement](#)


You are here: [EPA Home](#) » [Enforcement](#) » Consent Decree and Stipulated Orders: East Bay Municipal Utility District

## Consent Decree and Stipulated Orders: East Bay Municipal Utility District


iv. Other field data collection methods such as dye testing; level sensors; CCTV; visual inspection; **focused electrode leak location**; laser; sonar; field reconnaissance during storm events; and other methods of detecting sources of Inflow and Rapid Infiltration.

d. Identify additional techniques for I&I identification and prioritization. These may include, but are not limited to, analysis of surface maps, rainfall-response data analysis, or hydrologic or hydraulic modeling.

# LEAK



electro<sup>®</sup>  
scaninc.



# IMMEDIATELY CHANGE YOUR SPECS

Defect	Repair Method
<p>Wrinkles or ridges exceeding 5% and up to 8% of pipe diameter outside of 120-degree invert arc.</p> <p>Wrinkles or ridges exceeding 2% and up to 8% of pipe diameter inside of 120-degree invert arc (except corrugations in CMP).</p>	<p>Grind to required tolerance. Grind to required tolerance within the lower 120-degrees of pipe to remove and point repair where needed to maintain minimum thickness, or else use procedure in accepted repair plan.</p> <p>If wrinkles or ridges exceed 8% of pipe diameter, you must remove CIPP.</p>
<p>Holes, tears, soft spots, and lifts up to 6 inches in major dimension.</p> <p>Delaminated areas up to 12 inches in major dimension; blistering or bubbling of the coating on CIPP surface present over a maximum of 5% of surface area.</p>	<p>Make point repair under manufacturer's recommendations.</p> <p>If defect covers a larger area, you must remove CIPP.</p>
<p>CIPP thickness less than calculated minimum thickness.</p>	<p>You must remove CIPP. If groundwater conditions allow, you may install a second CIPP within the first CIPP that produces a similar dimension ratio to the first CIPP, or else use procedure in accepted repair plan.</p>
<p>Annular space at lateral connection or at end of CIPP or infiltration at lateral opening.</p>	<p>Seal with quick-set epoxy mortar, high viscosity epoxy or a hydrophilic vulcanized expansive rubber strip.</p>



# NEVER GRIND DOWN WRINKLES!


Defect	Repair Method
Wrinkles or ridges exceeding 5% and up to 8% of pipe diameter outside of 120-degree invert arc.	<b>Grind to required tolerance.</b> <b>Grind to required tolerance within the lower 120-degrees of pipe to remove and point repair where needed to maintain minimum thickness, or else use procedure in accepted repair plan.</b>
Wrinkles or ridges exceeding 2% and up to 8% of pipe diameter inside of 120-degree invert arc (except corrugations in CMP).	
Holes, tears, soft spots, and lifts up to 6 inches in major dimension.	If wrinkles or ridges exceed 8% of pipe diameter, you must remove CIPP.
Delaminated areas up to 12 inches in major dimension; blistering or bubbling of the coating on CIPP surface present over a maximum of 5% of surface area.	Make point repair under manufacturer's recommendations.  If defect covers a larger area, you must remove CIPP.
CIPP thickness less than calculated minimum thickness.	You must remove CIPP. If groundwater conditions allow, you may install a second CIPP within the first CIPP that produces a similar dimension ratio to the first CIPP, or else use procedure in accepted repair plan.
Annular space at lateral connection or at end of CIPP or infiltration at lateral opening.	Seal with quick-set epoxy mortar, high viscosity epoxy or a hydrophilic vulcanized expansive rubber strip.

# BEST PRACTICE

# THREE STEPS TO ZERO.

Date	Pipe ID	Diameter	Pipe Type	Distance (ft)	Small Defects	Medium Defects	Large Defects	GPM	GPD	GPD/IDM
11/19/2015	<div>A</div> 1-35 - 1-34	8	VCP	395.1	64	2	1	16.46	23,702	39,592
				Distance (ft)	Small Defects	Medium Defects	Large Defects	GPM	GPD	GPD/IDM

Test






# THREE STEPS TO ZERO.

Date		Pipe ID	Diameter	Pipe Type								
11/19/2015	A	1-35 - 1-34	8	VCP	395.1	64	2	1	16.46	23,702	39,592	
3/16/2016	B	1-35 - 1-34	8	CIPP	391.3	0	0	2	15.22	21,917	36,968	
					Distance (ft)	Small Defects	Medium Defects	Large Defects	GPM	GPD	GPD/IDM	


Test

A



Inspect

B




# THREE STEPS TO ZERO.

Date		Pipe ID	Diameter	Pipe Type								
11/19/2015	A	1-35 - 1-34	8	VCP	395.1	64	2	1	16.46	23,702	39,592	
3/16/2016	B	1-35 - 1-34	8	CIPP	391.3	0	0	2	15.22	21,917	36,968	
6/29/2016	C	1-35 - 1-34	8	CIPP	394.8	1	0	0	0.20	288	481	
					Distance (ft)	Small Defects	Medium Defects	Large Defects	GPM	GPD	GPD/IDM	


Test

A



Inspect

B



Accept

C





Mackenzie App

Mackenzie@Electroscan.com

315-857-8845



**THANK YOU!**





**ANSWER**

**QUESTION**